Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE8491/1

Work Order Type: Weatherization Audit Name: Audit DE8491

CLIENT INFORMATION

Client Name: Address:

Client ID: Client 50005DE8491

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE **Agency Phone:** (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

ctual		
nit Cost Total		
Total:		
Inspected		
Actual		
nit Cost Total		
Total:		

Measure 3 D	WH Pipe Insulation			Componen	ts		ı	Inspected
Comment								
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
Measure 4 At	ttic Ins. R-38			Componen				Inspected
Comment		Unite	Otiv	Estimated			Actual	
	Description / Comment Attic Insulation - Blown	<i>Units</i> SqFt	Qty 960	-		Qty		Inspected Total
Comment# Material / Labor1 Insulation	Description / Comment			Estimated			Actual	
Comment # Material / Labor	Description / Comment Attic Insulation - Blown			Estimated			Actual	
Comment# Material / Labor1 Insulation	Description / Comment Attic Insulation - Blown			Estimated			Actual	
Comment# Material / Labor1 Insulation	Description / Comment Attic Insulation - Blown	SqFt	960	Estimated		Qty	Actual	
# Material / Labor 1 Insulation Other Detail	Description / Comment Attic Insulation - Blown	SqFt	960	Estimated Unit Cost		Qty	Actual Unit Cost	
Comment# Material / Labor1 Insulation	Description / Comment Attic Insulation - Blown	SqFt	960	Estimated Unit Cost		Qty	Actual Unit Cost	
# Material / Labor 1 Insulation Other Detail	Description / Comment Attic Insulation - Blown	SqFt	960	Estimated Unit Cost		Qty	Actual Unit Cost	

Measure 5 Storm		Components Back, North, Front					Inspected	
Comment								
				Estimated	<u>'</u>		Actual	
# Material / Labor D	escription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows S	torm Window	SqFt	120					
2 Labor S	torm Window	SqFt	120					
3 Other S	torm Window	Each Window	10					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:						1		
Measure 6 CO Mo	nitor is Needed			Componen	ts		ı	Inspected
	nitor is Needed			Componen Estimated			Actual	Inspected
Comment	nitor is Needed	Units	Qty	-		Qty		Inspected
Comment # Material / Labor D		<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
# Material / Labor D 1 Health and Safety C Items	escription / Comment			Estimated	1	Qty	Actual	
# Material / Labor D 1 Health and Safety C Items	description / Comment CO monitor	Each	1	Estimated	1	Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor Labor 	description / Comment CO monitor	Each	1	Estimated	1	Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor Labor 	description / Comment CO monitor	Each	1	Estimated	1	Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor Labor 	description / Comment CO monitor	Each Hour	1	Estimated	1		Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor Labor 	description / Comment CO monitor	Each Hour	1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor D Health and Safety Items Labor Labor Labor C Other Detail	description / Comment CO monitor	Each Hour	1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor D 1 Health and Safety Items 2 Labor La Other Detail	description / Comment CO monitor	Each Hour	1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor D Health and Safety Items Labor Labor Labor Cother Detail	description / Comment CO monitor	Each Hour	1	Estimated Unit Cost	1		Actual Unit Cost	